FIELD INSPECTION REPORT

D	ate of Inspection :		CTION REPORT	
D)	Division: District:			
Ni	Name of the Road: Length (km): Length			
Sel	heme/Programme:	MATALLEN HOLOR	Pitch round to Kurmi To	A.
		I WATELANDE	Marian Control of the	
Sta	tus of the Project:	Ongoing/Complete	Road Id No.: 3\60850\2	23
	rk is a case of:	New Connectivity/I	Jp gradation/ Maintenance	
SL	No.	Parameters to	pp gradation/ Maintenance	
1	Pavement	200	ne checked	Remark
a)	Road Junction condition			
b) Condition of St				S/U
c) Riding Quality				S/U
d) Road Camber				S/U
e)	- Carrioti			S/U
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No	
1)	Contraction Joints provided or not (CC Pavement)		V	
g)	(c) Compaction of flank/slope & rai		ifany	Yes/No
2.	Cross Drainage			Yes/No
1)		walls in Lluma sin	国际政策联系的	
)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U	
) -	Condition of Abutment & Wing walls, Slab in RCC culverts		Slab in RCC culverts	S/SRI/U
A STATE	Road Furniture	Condition of railings/slab/approach for Bridges		
		State of the state		
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
	Compliance Histor	y	BREETEN TO THE TENEDON	530 m 5 2 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m 1 m
15	Status of ATR's & a	ny others	13 mars of the second	
-		Maria Ma		410

Overall Rating

5

(Signature)

NAME: Radondon Porsed y Swind dut

DESIGNATION: JES A.E.

3

AB