FIELD INSPECTION REPORT

	spection: 16.	01. 2021	District: W. Champoran	
vision :	Bellean	0-	Length (km): 1.275 K.4	
			3. Lu tolo to Pakhoulia	
heme/P		MAINTENANC	Road Id No.:	
	No.: BR. 37	Opening/Comp	leted/Under Maintenance UNDER	Naint.
	the Project:	New Connectiv	ity/Up gradation/ Maintenance Main	Connection
500a	Case on		nyto-be-checked	Remerks
4	Birement			
a)	Road Junction condition			√S/U
b)	Condition of Surfacing			\S/U
c)	Riding Quality			~8/U
d)	Road Camber			SN
e)	Whether free from defects such as visible cracks, exposed yes/No aggregates in case of CC Pavement.			
n	Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slope & raincuts if any Yes/No			
. 3.	Cross Brainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/			
c)	Condition of railings/slab/approach for Bridges S/SRI/			
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4	Compliance History			
B)	Status of ATR's & any others			

/	/	
Satisfactory (S)	15,	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

(Signature)

NAME: SUNIL WUNDER

DESIGNATION: J.E