Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs: - Gyan Viblakar

2 Name of Block/Road: Repair of road from motion pur to Rosti (Bocheha)

(A) For Road: \checkmark

- 1. Damage Location/Chainage :- 0.500 km; 0.700 km, 0.950 km, 2.10t
 2. Damage Length :- 619.30 m

 1. Tooker, 0.950 km, 2.10t

 1. Tooker, 1.50 km, 2.10t

 2. Damage Length :- 619.30 m

- 3. Nature of Damage
- 4. Details of Restoration Works :-
- Material being used in Restoration works:- Brick bets. (i)
- Equipment's/Tools being used in Restoration works:-(ii)
- Procedure taken up in Restoration works: (0.61930km)
 Restored Length :- 0.619 km (iii)

:-

- Restored Length (iv)

(B) For Bridge: *

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works :-
- Material being used in Restoration works:-(i)
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

Signature

(Name of Inspection) EE

RUD WOR DIVISION. myzaffar bur East-L

GENERAL ABSTRACT

Name of Road

Repair of road from Mohanpur to Roshi

District

Muzaffarpur

Block

Bochaha

Division

Muzaffarpur East-2

Length of Road (in Km)

2.800 Km

DESCRIPTION	
	AMOUNT (LAKHS)
	18.227
Sand Filling	0.000
Sand bag	
Rambaa Dilaa	0.000
	0.000
	18.227
OST OF PROJECT IN LACS =	18.227
	DESCRIPTION Jhama metal Sand Filling Sand bag Bamboo Piles GRAND SUB TOTAL DST OF PROJECT IN LACS =

SAY): 18.23 lac

Technically Approved for Ps 18.23 lac (pupees eighteen lac, twenty three thousand only).

pud work circle