

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - ८०८ गयन प्रब्लोक

2. Name of Block/Road - ८०८ प्रयागवारी to Beou (Haighat)

A. For Road ✓

1. Damage Location/Chainage : 2.8 km, 2.95 km, 3.20 km, 3.60 km, 3.80 km, 4.0 km
2. Damage Length : 0.4268 km (Length = 4.0 km)
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Brick bats
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length : 0.4268 km

B. For Bridge ✗

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration works:
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

Signature of JE/AE/EE


24.12.20
Signature

(Name of Inspector)

• EE
RWD work Division
myzaffarbux East-1

GENERAL ABSTRACT

Name of Road L083 Pravagwari to Berua (VR57)

District Muzaffarpur

Block Gaighat

Division Muzaffarpur East-2

Length of Road (in Km) 4.000 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	10.507
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	10.507
TOTAL COST OF PROJECT IN LACS =		10.507

SAY 10.51 LAC

[Signature]
20/12/20
JE
RWD

[Signature]
20/12/20
AE
RWD

[Signature]
20/12
EE
RWD

Technically Approved for Rs 10.51 Lac.
(Rupees ten Lac, fifty one thousand only.)

[Signature]
4-1-21
SE
RWD work circle
muzaffarpur