

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan ~~blakay~~

2 Name of Block/Road :- Reo Road to Bisunpur Khetal (Bachaha)

(A) For Road:

1. Damage Location/Chainage :- 0.250km, 0.500km, 0.70km, 0.850km, 1.10km
2. Damage Length :- 225.0m (0.225 km) (Length = 1.210 km)
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- brick bats.
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.225km

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE

Signature

(Name of Inspection)

EE
PWD WORK DIVISION
muzaffarpur Cell-1

GENERAL ABSTRACT

Name of Road REO Road to Bisunpur Khetai

District Muzaffarpur

Block Bochaha

Division Muzaffarpur East-2

Length of Road (in Km) 1.210 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	9.074
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	9.074
TOTAL COST OF PROJECT IN LACS =		9.074

Says. 9.07 Lac

Santosh Kumar
20/12/2020

JE
20/12/20

RWD

AE
20/12/20

RWD

EE
20/12/20

RWD

Technically Approved for Rs. 9.07 Lac.
(Rupees nine Lac, seven thousand only.)

17/12/21
SE
RWD work circle
muzaffarpur