harbha

FIELD INSPECTION REPORT

Date of Inspection: 17 01 2021 District: Chapra.				
Division: (happy -) Length (km): 1.226 Lyd.				0
Nam	Name of the Road: Basant Basar to Bhuisaw Koeri fuly, yagar			
Schen	Name of the Road: Bosant Bazer to Bhuizaw Koeritoly, yadar Scheme/Programme: MAINTENANCE Morgsy (XIDB)			
	Road Id No.:			fash fac
	s of the Project:	Ongoing/Completed/Under Maintenance		
BULL BURNES	is a case of:	New Connectivity/Up gradation/ Maintenance		
SI. No	0.	Parameters to be checked	Remarks	
1. Pavement				1
a)	Road Junction	condition	S/U	7
b)	Condition of St	urfacing	S/U	1
c)	Riding Quality		S/U	
d)	Road Camber		S/U	
e)	Whether free aggregates in ca	from defects such as visible cracks, exp se of CC Pavement.	osed Yes/No	
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2.	Cross Drainage			
a)		ad walls in Hume pipe culverts including its pair		
b) ·		utment & Wing walls, Slab in RCC culverts	S/SRI/U	7
c)		ings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture			
a)	Whether sign b stones/Pavement	oards/informatory/cautionary Board/km & 2 road markings are provided and maintained	200m Yes/No	
4.	Compliance His	lory : 12-2		
a)	Status of ATR's	& any others		

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

12/1/2021 audela

(Signature)

NAME:

DESIGNATION:

Scanned with CamScanner