FIELD INSPECTION REPORT

	113 12021 Distri	cl: Nalanda,	1
Division	: Bihassharil . Lengt	h (km):	
	me kind: Benaz-Sukathra Po)
Package	Togramme: MAINTENANCE M	mast (gen)	
	KORG	Id No.:	
	Garage State of Contract		
Sl. No.	The state of the s		ph-1
	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U WOZ
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage	dan die bei and bei de	
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
-4.	Compliance History		
a)	Status of ATR's & any others		No
Overall R			

Satisfactory (S)	0
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Mukesh Yadan

DESIGNATION:

¬ · · · ·

Scanned with CamScanner

Scanned with CamScanner