FIELD INSPECTION REPORT

Date of L	Innet:				
Date of Inspection: 17/1/12/21 District: Halanday					
Length (km):			Length (km):		
Name of the Rond: Benaz Mahmudahad Road To Manpus					
Post in MAINTENANCE MMGS Y					
Kond 10 (10)					
-	The state of the s				
SI. No.	Parameters to be checked			Remarks	
, 1.	Pavement				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes∕No	
2.,	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4.	Compliance History				
a)	Status of ATR's & any others				

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

. Land Problem Work Not Chartel.

(Signature) 7/12021

NAME: Mulces & Yaday

DESIGNATION: SE

Scanned with CamScanner

MA