FIELD INSPECTION REPORT

	in 11 1-2021 District: Develohinger	
	nspection: 14-1-2021 District: Derschanger Length (km): 5.41 Lm	-
Division	the Road: Andama PMSY Path Be ughra. Itarija	em lota
Name of	Buggramme: IMAINTENANCE On Gamey	
Package	Road Id No.:	
Package	- Ongoing/Completed/Under training	
Work is	the Project: Ongoing Complete a case of: New Connectivity/Up gradation/ Maintenance	
SI. No.	Parameters to be checked	Remarks
1.	Payement	
a) .	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
c) -	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a) -	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U \$
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a) .	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No O
4. (c	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Hofe! - Work is on 4SB Stage.

NAME: Vinek Kumoz DESIGNATION: JE., Bestordungs