FIELD INSPECTION REPORT

	Inspection:	08.01.2021	District:	Buxar		
Division				oo KM		
		-	soud to James	a Tola.		
The second second	Programme:	MAINTENANCE	Road Id No.:			
Package Status of	the Project:	Ongoing/Complete	ed/Under Maintenance			
-	a case of:		Up gradation/ Mainter			
SI. No.		Parameters to			Remarks	11
1.	Pavement					
a)	Road Junction condition Condition of Surfacing Riding Quality Road Camber Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Contraction Joints provided or not (CC Pavement) Compaction of flank/slope & raincuts if any				S/U _	S
b)					S/U _S	
c)						
d)					10 S	
e)					Yes/No	**
f)					Yes/No	MA
g)					Yes/No	No
2.	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting				S/SRI/U	-5
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				S/SRI/U	MA
c)	Condition of railings/slab/approach for Bridges				S/SRI/U	HH
3.	Road Furniture					
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				Yes/No M	novido
4.	Compliance History					
a)	Status of ATR	s of ATR's & any others			Hor	
Overall	Rating :					
- Totali	· ·	Satisfactory (S)			1. 8 11	1
			requires Improveme	nt (SRI)	-	11
		Unsatisfactory (U)			1

1-E 08/01/2021

NAME: Dunson Kesall -

A. E. Kesall-

(Signature)