

## Inspection Report for Flood Damage Work

Date.: .....26/12/2020.....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Sahebganj

3. Name of Road/Bridge – Bisunpur patti (Rajwara chowk se purab) - Jagdishpur

A. for Road

1. Damage Location/Chainage : 0.600 TO 1.200

2. Damage Length : 36m

3. Nature of Damage : 1/3rd Road crest with subgrade shoulder infill

4. Details of Restoration Works :


i. Material being used in Restoration works : Brick Ballast —

ii. Equipments/Tools being used in Restoration Works : Tractor, JCB etc

iii. Procedure taken up in Restoration works :

iv. Restored Length :

B. for Bridge

1. Damage Location/Chainage : 

2. Damage Length :

3. Nature of Damage :


4. Details of Restoration Works :


i. Material being used in Restoration works :


ii. Equipments/Tools being used in Restoration Works :


iii. Procedure taken up in Restoration works :

iv. Restored Length :

  
J.E.

  
A.E.

  
Executive Engineer,  
R.W.D. Works Division,  
Muzaffarpur west

  
Signature  
(Name of Inspector)