

## Inspection Report for Flood Damage Work

Date.: ...26.12.2020...

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Paroo

3. Name of Road/Bridge – Dewaria To Dharpari

A. for Road

1. Damage Location/Chainage : 3.75KM to 4.75KM.

2. Damage Length : 113M.

3. Nature of Damage : Breach at Road crust with embankment.

4. Details of Restoration Works :

i. Material being used in Restoration works : Bricks Ball, Local sand.

ii. Equipments/Tools being used in Restoration Works : Tractor, J.C.B, Roller

iii. Procedure taken up in Restoration works : First Bricks Ball filling in breach portion.  
Then Topping by local sand.

iv. Restored Length : — 113M.

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

26.12.20

J.E.

26/12/2020

A.E.

26/12/20  
Executive Engineer,  
R.W.D. Works Division,  
Muzaffarpur west

26/12  
Signature  
(Name of Inspector)