

(6)

Inspection Report for Flood Damage Work

Date.:26.12.2020.....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Paroo

3. Name of Road/Bridge – Hirapur PWD Road To Pichpura

A. for Road

1. Damage Location/Chainage : 90M, 320M, 700M, 1200M.

2. Damage Length : 69M.

3. Nature of Damage : Break at Road Cross with Embankment.

4. Details of Restoration Works :

i. Material being used in Restoration works : Bridge Ball, local sand.

ii. Equipments/Tools being used in Restoration Works : Tractor, J.C.B, Roller

iii. Procedure taken up in Restoration works : First - Bridge Ball filling in break portion
Then - Top by local sand.

iv. Restored Length : — 69.00M

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

26.12.20
J.E.

26/12/20
A.E.

26/12/20
Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west

Signature
(Name of Inspector)