

## Inspection Report for Flood Damage Work

Date.: .....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Kanti

3. Name of Road/Bridge – Pitch Road To Sainchapra Devanand

A. for Road

1. Damage Location/Chainage : CH- 100m, 150m, 170m, 250m, 350m, 500m  
700m, 800m, 850m, 950m

2. Damage Length : 265m

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works : soil, Brick Bats, Local sand, Sand Bag, Bamboo

ii. Equipments/Tools being used in Restoration Works : Tractor, Roller, JCB

iii. Procedure taken up in Restoration works :

iv. Restored Length : 265m

B. for Bridge

1. Damage Location/Chainage : N/A

2. Damage Length : N/A

3. Nature of Damage :


4. Details of Restoration Works :

i. Material being used in Restoration works :


ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

  
24/12/2020  
J.E.

  
26/12/2020  
A.E.

  
Executive Engineer,  
R.W.D. Works Division,  
Muzaffarpur west

  
Signature  
(Name of Inspector)