

Inspection Report for Flood Damage Work

Date.: .....26.12.2020.....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Paroo

3. Name of Road/Bridge – PWD Malahi Road To Jainpur

A. for Road

1. Damage Location/Chainage : 3.00 KM

2. Damage Length : 16.00 M.

3. Nature of Damage : Break at road crest with Embankment

4. Details of Restoration Works :

i. Material being used in Restoration works : Bricks Bats, Local Sand

ii. Equipments/Tools being used in Restoration Works : Tractor, J.C.B, Roller

iii. Procedure taken up in Restoration works : First- Bricks bats filling in break portion.  
Then- Topping by local Sand.

iv. Restored Length : — 16.00 M.

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :


4. Details of Restoration Works :

i. Material being used in Restoration works :


ii. Equipments/Tools being used in Restoration Works :


iii. Procedure taken up in Restoration works :

iv. Restored Length :

  
J.E.

  
A.E.

  
Executive Engineer,  
R.W.D. Works Division,  
Muzaffarpur west

  
Signature  
(Name of Inspector)