Inspection Report for Flood Damage Work

Date.:			
1. Name of PIUs – Executive Engin	eer, R.W.D	, Works, Division	, Muzaffarpur West
2. Name of Block – Kanti			•
3. Name of Road/Bridge – Kanti mo PMGSY		SY sadak se shine	chowk bus stand se gopalpur
A. for Road - N/A			
1. Damage Location/Chainage	: 10		
2. Damage Length	: 2.0	o m q k	
3. Nature of Damage	: <u>}</u>		
4. Details of Restoration Works	: >		
i. Material being used in Resto	ration work	s:	
ii. Equipments/Tools being use	d in Restora	tion Works: 🗴	
iii. Procedure taken up in Restor	ration works	: x	
iv. Restored Length:			
B. for Bridge			
1. Damage Location/Chainage	: CH	- 0.100 Km)
2. Damage Length	: 2.	- 0.100 Km	
3. Nature of Damage	:		
4. Details of Restoration Works	:		
i. Material being used in Resto	ration work	s: Brick's Bo	t, # H.P, Local Sond
ii. Equipments/Tools being use	d in Restora	tion Works: Tra	der, holler, TCB
iii. Procedure taken up in Restor	ation works	:	
iv. Restored Length:	2.001	m	
domale Rollingo		1/10/211	S) May

Executive Engineer, R.W.D. Works Division, Muzaffarpur west

J.E.

Name of Inspector)