

Inspection Report for Flood Damage Work

Date.: 26/12/2020

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Paroo

3. Name of Road/Bridge – Babhangama Kurmi Tola to Baya Jagdishpur

A. for Road

1. Damage Location/Chainage : 0.800 KM

2. Damage Length : 16.00 M

3. Nature of Damage : Breach at Road Cross with Embankment

4. Details of Restoration Works :

i. Material being used in Restoration works : Brick Bala, Local Sand

ii. Equipments/Tools being used in Restoration Works : Tractor, J.C.B, Roller

iii. Procedure taken up in Restoration works : First - Brick Bala filling in breach portion
Then - Topping by local sand.

iv. Restored Length : — 16.00 M

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :

26/12/20
J.E.

26/12/20
A.E.

26/12/20
Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west

26/12/20
Signature
(Name of Inspector)