

Inspection Report for Flood Damage Work

Date.: ...26.12.2020.....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West
2. Name of Block – Paroo
3. Name of Road/Bridge – Kadaariya Mango High School to Jagadishpur via PMGSY Road

A. for Road

1. Damage Location/Chainage : 1.75 KM
2. Damage Length : 5.5 M
3. Nature of Damage : Breach at road crest with embankment.
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Jhama Metal (Binko Boko), Local Sand.
 - ii. Equipments/Tools being used in Restoration Works : Tractor, J.C.B, Roller
 - iii. Procedure taken up in Restoration works : First - Binko Boko Filling in breach portion.
Then - Topsoil by local sand.
 - iv. Restored Length : — 5.50 M

B. for Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration Works :
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :

J.E.

A.E.

Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west

Signature
(Name of Inspector)