

Inspection Report for Flood Damage Work

Date.:26.12.2020.


1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West
2. Name of Block – Paroo
3. Name of Road/Bridge – PMGSY Road Baijalpur Bangali Paswan ke Ghar to Paras Ray ke Ghar Tak via Baijalpur Paswan Tola West


A. for Road


1. Damage Location/Chainage : 20M, 450M, 650M, 800M, 1000M
2. Damage Length : 150M
3. Nature of Damage : Breach at Road Crest with Embankment
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Bricks Bats, Local Sand.
 - ii. Equipments/Tools being used in Restoration Works : - Tractor, J.C.B, Roller
 - iii. Procedure taken up in Restoration works : First - Bricks Bats filling in breach portion. Then - Topping by Local Sand.
 - iv. Restored Length : 150M


B. for Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration Works :
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :


J.E.


A.E.


Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west


Signature
(Name of Inspector)