Inspection Report for Flood Damage Work

Date.: 23/12/2020	
1. Name of PIUs – Executive Engi	ineer, R.W.D., Works, Division, Muzaffarpur West
2. Name of Block – Sahebganj	
3. Name of Road/Bridge – Makari	Tola SH-74 Mushhar Tola Narayan Chowk Tak
A. for Road	
1. Damage Location/Chainage	: 070 40M
2. Damage Length	: 070 40M : 525m
3. Nature of Damage	:
4. Details of Restoration Works	: shame model Bricus But & local Sane
i. Material being used in Rest	toration works:
ii. Equipments/Tools being us	ed in Restoration Works :
iii. Procedure taken up in Rest	oration works:
iv. Restored Length:	25M
B. for Bridge	
1. Damage Location/Chainage	· : (
2. Damage Length	: \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
3. Nature of Damage	: 142-0
4. Details of Restoration Works	
i. Material being used in Rest	oration works:
ii. Equipments/Tools being us	ed in Restoration Works:
iii. Procedure taken up in Resto	oration works:
iv. Restored Length:	
J.E. 12 26/12 A.E.	Executive Engineer, R W D. Works Division (Name of Ingrestor)

R.W.D. Works Division,

Muzaffarpur west

(Name of Inspector)