

## Inspection Report for Flood Damage Work

Date.: .....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West
2. Name of Block – Kanti
3. Name of Road/Bridge – Barkagoan Aasnagar PMGSY Road me Bakatpur state Boding choketo Jhitkahi Siman Hanuman Mandir ke pas

### A. for Road

1. Damage Location/Chainage : CH - 1100m, 1200m, 1500m, 2200m, 2800m
2. Damage Length : ~~303m~~ 303m
3. Nature of Damage :
4. Details of Restoration Works :
  - i. Material being used in Restoration works : - soil
  - ii. Equipments/Tools being used in Restoration Works : Tractor, Roller, JCB
  - iii. Procedure taken up in Restoration works :
  - iv. Restored Length : - 303m

### B. for Bridge


1. Damage Location/Chainage : N/A
2. Damage Length : N/A
3. Nature of Damage :
4. Details of Restoration Works :
  - i. Material being used in Restoration works :
  - ii. Equipments/Tools being used in Restoration Works :
  - iii. Procedure taken up in Restoration works :
  - iv. Restored Length :


  
26/12/2020

J.E.

  
26/12/2020

A.E.

  
Executive Engineer,  
R.W.D. Works Division,  
Muzaffarpur west

  
Signature  
(Name of Inspector)