

## Inspection Report for Flood Damage Work

Date.: ....26/12/2020.....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Paroo

3. Name of Road/Bridge – PMGSY Road Dharfari to Paswan Tola and Ray Tola

A. for Road

1. Damage Location/Chainage : 17 plus (0.50km to 2.50km)

2. Damage Length : 201.70m.

3. Nature of Damage : Break at road crest with embankment.

4. Details of Restoration Works :

i. Material being used in Restoration works : Bricks Ball, Local Sand.

ii. Equipments/Tools being used in Restoration Works : Tractor, J.C.B, Roller.

iii. Procedure taken up in Restoration works : First - Bricks Ball filling in breach portion. then - Topping by Local Sand.

iv. Restored Length : ——— 201.70m.

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :


4. Details of Restoration Works :


i. Material being used in Restoration works :


ii. Equipments/Tools being used in Restoration Works :


iii. Procedure taken up in Restoration works :

iv. Restored Length :

  
J.E.

  
A.E.

  
Executive Engineer,  
R.W.D. Works Division,  
Muzaffarpur west

  
Signature  
(Name of Inspector)