

### Inspection Report for Flood Damage Work

Date.: .....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West
2. Name of Block – Kanti
3. Name of Road/Bridge – Vijayi Chhapra Gandak Bandh PMGSY Road to Kushti Chawk NH-77 tak via Vijayi Chhapra School and Ashok Sahni ke Ghar Hote Hue


**A. for Road**


1. Damage Location/Chainage : 45m CA-0.55 km
2. Damage Length : 45.00 m
3. Nature of Damage :
4. Details of Restoration Works :
  - i. Material being used in Restoration works : - soil
  - ii. Equipments/Tools being used in Restoration Works : Tractor, Roller, JCB
  - iii. Procedure taken up in Restoration works :
  - iv. Restored Length : 45.00 m

**B. for Bridge**

1. Damage Location/Chainage : N/A
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
  - i. Material being used in Restoration works :
  - ii. Equipments/Tools being used in Restoration Works :
  - iii. Procedure taken up in Restoration works :
  - iv. Restored Length :

  
J.E.

  
A.E.

  
Executive Engineer,  
R.W.D. Works Division,  
Muzaffarpur west

  
Signature  
(Name of Inspector)