

## Inspection Report for Flood Damage Work

Date.: .....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West
2. Name of Block – Kanti
3. Name of Road/Bridge – Bangra Kumhar Tola REO Sadak to Mithanpura Bindeswar Ray ke Ghar ke Pas PWD Sadak Tak via Bangra Kumhar Tola and Madhya School Tak

### A. for Road

1. Damage Location/Chainage : *D:80  
:800 kr*
2. Damage Length : *28.10 m*
3. Nature of Damage :
4. Details of Restoration Works :
  - i. Material being used in Restoration works : *soil, brick's Bat, local sand, sand bags,*
  - ii. Equipments/Tools being used in Restoration Works :
  - iii. Procedure taken up in Restoration works :
  - iv. Restored Length : *28.10 m*

### B. for Bridge

- N/A*
1. Damage Location/Chainage : *x*
  2. Damage Length : *x*
  3. Nature of Damage : *x*
  4. Details of Restoration Works : *x*
    - i. Material being used in Restoration works : *x*
    - ii. Equipments/Tools being used in Restoration Works : *x*
    - iii. Procedure taken up in Restoration works : *x*
    - iv. Restored Length : *x*

*[Signature]*  
26/11/20  
J.E.

*[Signature]*  
26/11/20  
A.E.

*[Signature]*  
Executive Engineer,  
R.W.D. Works Division,  
Muzaffarpur west

*[Signature]*  
Signature  
(Name of Inspector)