

## Inspection Report for Flood Damage Work

Date.: ....26/12/2020.....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West
2. Name of Block – Sahebganj
3. Name of Road/Bridge – Panchrukhiya Dhala Se Tulsi Chowk Hote Huye to Hussepur Siwan  
Mushari Pull SH Road Tak

### A. for Road


1. Damage Location/Chainage : 0.0 KM TO 1.0 KM
2. Damage Length : 300 m
3. Nature of Damage : Road cut with subgrade shoulder eroded in flood.
4. Details of Restoration Works :
  - i. Material being used in Restoration works : G.W & sand bag.
  - ii. Equipments/Tools being used in Restoration Works : eroded part of road filled
  - iii. Procedure taken up in Restoration works : with cement & Brice bags
  - iv. Restored Length : —


### B. for Bridge

1. Damage Location/Chainage : (
2. Damage Length : )
3. Nature of Damage : NE
4. Details of Restoration Works :
  - i. Material being used in Restoration works :
  - ii. Equipments/Tools being used in Restoration Works :
  - iii. Procedure taken up in Restoration works :
  - iv. Restored Length :

  
J.E.

  
A.E.

  
Executive Engineer,  
R.W.D. Works Division,  
Muzaffarpur west

  
Signature  
(Name of Inspector)