

FIELD INSPECTION REPORT

Date of Inspection: 12.1.24	District: East Champaran
Division: Energy	Length (km): 0.700 KM
Name of the Road: Laxmi Parkai talga to Loto	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New/Continuity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting.	✓ S/SR/U
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	✓ S/SR/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SR/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ S/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :	Satisfactory (S)	S (S)
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

(Signature)

NAME: Manish Kumar

DESIGNATION: J.E R.W.D. Energy



Shot on Y12
Vivo AI camera