

# FIELD INSPECTION REPORT

Date of Inspection : 10/12/20	District: Sevan
Division : Mahasagar	Length (km): 3.350 km
Name of the Road: Sevan Paigambarpur Path to Indapur	
Scheme/Programme: MAINTENANCE / PMGSY	
Package No.: BR-34R-305	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b> B.T. + Cell filled	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing Damaged from flood/heavy rain	✓ S/U ✓
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts N/A	S/SRI/U
c)	Condition of railings/slab/approach for Bridges ✓	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating : *this road is damaged from flood & heavy rain at some places*

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	U

Ravi Sagar Das

NAME:

DESIGNATION:

J.E

*10/12/20*  
(Signature)