## FIELD INSPECTION REPORT

Date	of Inspection: 18/01/21	District: Samastipur		
Division: RWD Dalsinghsarai		Length(km): 0.450		
	ne of Road: Loss to Salni To	ola		
	eme / Programme: MAINTENANCE			
	kage No:	Road Id No: GTSNY		
	us of the Project: Ongoing/Completed/Under			
	rk is a case of: New Connectivity/ Up g			
Sl. No	Parameters to be C		Remarks	
1	Pavement			
a)	Road Junction Condition		S	
b)	Condition of Surfacing		S	
c)	Riding Quality		2	
d)	Road Camber		2	
e)	Whether free from defects such as visible cra aggregates in case of CC Pavement	cks, exposed	SRI	
f)	C C		2	
g)	Compaction of flank/slope & raincuts if any		SRI	
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing walls , Slab in RCC culverts			
c)	Condition of railings/slab/approach for Bridge		-	
3	Road Furniture			
a)	Whether sign boards/information/cautionary stones/Pavement road markings are provided		U	
4	Compliance History			
a)	Status of ATR's & any others			

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	SRI
Unsatisfactory(U)	

oliva (Signature)

NAME: Despor Clondra Sinta DESIGNATION: J.E