FIELD INSPECTION REPORT

ate	of Inspection: 18/61/21	District: Samastipur	
ivision: RWD Dalsinghsarai		Length(km): 0.335	
lam	e of Road: LO37 to Ma	Lto Tola	
iche	me / Programme: MAINTENANC	E	
ack	inge No:	Road Id No: GTSAY	
Stati	us of the Project: Ongoing/Completed		
Wor	A is a case of: New Connectivi	ity/ Up gradation/ Maintenance	
SL. No	Parameters to be Checked		Remarks
1	Pavement		
a)	Road Junction Condition		2
6)	Condition of Surfacing		2
(2)	Riding Quality		5
d)	Road Camber		2
(e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		5
1)	Construction Joint provided or not(CC Pavement)		2
g)	Compaction of flank/slope & raincuts if any		SRI
2	Cross Drainage		
2)	Condition of head walls in Hume pipe culverts including its painting		-
b)	Condition of Abutment & Wing walls , Slab in RCC culverts		Transition of
(c)	Condition of railings/slab/approach for Bridge		
3	Road Furniture		
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		S
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory(S)	THE PERSON NAMED IN
Satisfactory but requires Improvement(SRI)	005
Unsatisfactory(U)	JR2

Aserta 18/01/21 (Signature)

NAME: Deepar Clandon Sinta DESIGNATION: J.E.