## FIELD INSPECTION REPORT

ate 01 11	nspection: 1	6/01/2021	District: Malanda		
Wision: Bihar Shant			Langth (lamba a flag)		
ame of	the Road: L	058 to kur	nardoh		
ackage	rogramme:	MAINTENANCI	E MMGSY (SC)		
	the Project:	0 1/0	Road Id No.:		
Vork is	a case of:	Ongoing/Comple	ted/Under Maintenance		
Sl. No.			y/Up gradation/ Maintenance		
1.	Parameters to be checked		Remarks		
	Pavement				
a) ,	Rond Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
Tal.	Compliance History			-	
a)	Status of AT	R's & any others		Hil	

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

16/01/2021

(Signature)

NAME: Binod Kumar Singh

DESIGNATION: J. B.