## FIELD INSPECTION REPORT

Date of	Inspection:	18.1.21	District: Begy_rs7	m
Division	n:	Beginsoni Link posal of	Length (km): $0.350  \text{Par}$	
		link posoloh	Bih Tola	
	/Programme:	MAINTENANCE		
Packagu			Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance  Work is a case of: New Connectivity/Up gradation/ Maintenance				
Work is	a case of:	· Printed to the state of the s	7.10	
Sl. No.	Parameters to be checked Remarks			
1.	Pavement			
a)	Road Junction condition			51 <i>5</i>
b)	Condition of Surfacing			S/U S
c)	Riding Quality			S/U
d)	Road Camber			S/L
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
1)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
(1)	Condition of head walls in Hume pipe culverts including its painting			S/SREL
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			
Ovarull	Rating :	(5)		
OACHIII	Satisfactory (S) Satisfactory but requires Improvement (SRI)			5
¥				
	•	Unsatisfactory (	U)	

1 1011.2)

(Signature)

NAME:

DESIGNATION: