FIELD INSPECTION REPORT

ate of Ir		District: Malanda	
ivision :		Length (km): 1.275 km	
ame of	the Road: 1060 To Murgo ya	chart (2 is a)	
	rogramme: MAINTENANCE	13 1 1 1 No. 4	
ickage	No.:	Road Id No.: Under Maintenance (work not	- started
	the Project: Ongoing/Completed/	gradation/ Maintenance	-
			Remarks
il. No.	Parameters to l	se enecked	
1.	Pavement		
a) .	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
n	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slah/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
74.	Compliance History		-
a)	Status of ATR's & any others		Nil

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Start 12021

(Signature)

NAME: Birned Kumar sulyh

DESIGNATION: F.E