

## Inspection Report for Flood Damage Work

Date:- 15.1.21

1 Name of PIUs :- Muzaffarpur East-2

2 Name of Block/Road :- (Link M1-158) Kabinistan to Shabir Pasrah


### (A) For Road:

1. Damage Location/Chainage :- 1st kta. 2nd
2. Damage Length :- 86.00m
3. Nature of Damage :- Fully road washed
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- concrete
  - (ii) Equipment's/Tools being used in Restoration works:- Tractor
  - (iii) Procedure taken up in Restoration works:
  - (iv) Restored Length :- 86.00m

### (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE

  
Signature  
Executive Engineer  
(Name of Inspector)  
Muzaffarpur East-1

## GENERAL ABSTRACT

Name of Road (Link No-158) Kabristan to Dhobindr Paswan

District Muzaffarpur

Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km) 1.600 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	24.943
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	1.307
	<b>GRAND SUB TOTAL</b>	<b>26.250</b>
<b>TOTAL COST OF PROJECT IN LACS =</b>		<b>26.250</b>

*(Signature)*  
8-1-21

JE  
RWD

*(Signature)*

AE  
RWD

*(Signature)*  
8/1/21  
EE  
RWD

*Mechanically approved for Rs. 26.250 lacs  
(Rupees twenty six lacs twenty five thousand only)*

*(Signature)*  
S.E.

RWD work circle  
muzaffarpur