Inspection Report for Flood Damage Work

Date:- 17.1.21

1 Name of PIUs: - Muzaffortez East-2.

2 Name of Block/Road: - PWD Rosa to cakeb Sahni ke eyher

(A) For Road:

1. Damage Location/Chainage :- 151 151 200 2 Damage Length :- 243. 3 wh

3. Nature of Damage :- Rued cutting ball ditchn

4. Details of Restoration Works:-

(i) Material being used in Restoration works:- Briefs beds

(ii) Equipment's/Tools being used in Restoration works:- Touth

(iii) Procedure taken up in Restoration works:

(iv) Restored Length :- 243.8 WW

(B) For Bridge:

1. Damage Location/Chainage :-

2. Damage Length :-

3. Nature of Damage :-

4. Details of Restoration Works:-

(i) Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length

Signature of JE/AE/EE

Signature

(Name of Inspection)

Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road

PWD Road to Saheb Sahni ke Ghar

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

1.100 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	6.311
2	Sand Filling	1.856
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	8.167
TOTAL COST OF PROJECT IN LACS =		8.167

JE

RWD

RWD

RWD

Techanically approved for B. 8-167 law (Rupees eight loves sixteen thousand Seven Lundowd only)

S-E RND 1000k conte