

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- minapur / malasudpur to mathraul


(A) For Road:

- ✓
1. Damage Location/Chainage :- 1.020 Km, 1.50 Km
 2. Damage Length :- 0.047 Km
 3. Nature of Damage :-
 4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick batts
 - (ii) Equipment's/Tools being used in Restoration works:- Trencher
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.047 Km

(B) For Bridge:

- X
1. Damage Location/Chainage :-
 2. Damage Length :-
 3. Nature of Damage :-
 4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE

Rwd mura-ghasipur East - 1

GENERAL ABSTRACT

Name of Road Makasudpur to Mathmaul

District Muzaffarpur

Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km) 2.433 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	3.550
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	3.550
TOTAL COST OF PROJECT IN LACS =		3.550

say 3.55 lac

[Signature]
11/1/21

JE
RWD

[Signature]
11/1/21

AE
RWD

[Signature]
11/1/21
EE
RWD

Technically approved for Rs 3.55 lac
(Rupees Three lac fifty five thousand only)

[Signature]
13.1.21
SE

RWD work circle
muzaffarpur