Inspection Report for Flood Damage Work

15-1.21 Date:-

1 Name of PIUs: - Muzaffartus East-2

2 Name of Block/Road: - Banghare Prop (Domba charren) to Therampur

(A) For Road:

1. Damage Location/Chainage :- 15+ & 2hd kray

:- 231.7 mb 2. Damage Length

:- sped cutting 3. Nature of Damage

4. Details of Restoration Works :-

Material being used in Restoration works:- ronck bets (i)

Equipment's/Tools being used in Restoration works:- Treety (ii)

Procedure taken up in Restoration works:

:- 231-7mtr Restored Length (iv)

(B) For Bridge:

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works :-
- Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road

Banghara PWD road (Doma Chowk) to Dharampur

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

2.329 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	7.900
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	7,900
TOTAL O	COST OF PROJECT IN LACS =	7.900

8-1.71

JE

RWD

ACOGO!M

AE

RWD

92811-1

RWD

Techanically Approved for B. 7.90 lace

RWD work circle