

## Inspection Report for Flood Damage Work

Date:- 17.1.21

1 Name of PIUs :- Muzaffarpur East-2

2 Name of Block/Road :- 470-1068 Jamuh Mathia main Road to Pakhahgati (V.P.S.)


### (A) For Road:

1. Damage Location/Chainage :- 1st 43rd km
2. Damage Length :- 54.5 m
3. Nature of Damage :- Gole cutting & bridge abutment cutting
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- Brack baki
  - (ii) Equipment's/Tools being used in Restoration works:- Tractor
  - (iii) Procedure taken up in Restoration works:
  - (iv) Restored Length :- 54.5 m

### (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE

  
17.1.21  
Signature  
Executive Engineer  
(Name of Inspection)  
R.W.D. Works Division  
Muzaffarpur East-1

## GENERAL ABSTRACT

Name of Road L070-L068 Jamin mathai main road to To Pakhnaha jitwar (VR55)

District Muzaffarpur

Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km) 2.500 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	5.102
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	5.102
TOTAL COST OF PROJECT IN LACS =		5.102

*M. S. 1.21*  
JE

RWD

*ASL 08/01/24*

AE

RWD

*2.500*  
EE  
RWD

*Technically approved for Rs 5.102 Lacs  
(Rupees five lac ten thousand two hundred only)*

*S. E.*

S-E

*RWD work circle  
Muzaffarpur*