

Inspection Report for Flood Damage Work

Date:- 15.1.21

1 Name of PIUs :- Muzaffarpur East-2

2 Name of Block/Road :- Lo 57 - Lo 76 to Rajar Mura (VR48)


(A) For Road:

1. Damage Location/Chainage :- 2nd km
2. Damage Length :- 45-m
3. Nature of Damage :- Gull & 3/4 cut due to flood water
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- brick beds
 - (ii) Equipment's/Tools being used in Restoration works:- Trench
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- 45-m

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature
Executive Engineer
(Name of Inspection)
R.W.D. Works Division
Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road L097-L076 to Bajar Munria (VR48)

District Muzaffarpur


Block Minapur


Division Muzaffarpur East-2

Length of Road (in Km) 2.700 Km


Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	5.220
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	5.220
TOTAL COST OF PROJECT IN LACS =		5.220


JE
RWD


AE
RWD


EE
RWD

Technically approved for Rs. 5.22 Lacs
(Rupees five Lacs twenty two thousand only)


S.E.

RWD work circle
Muzaffarpur