Inspection Report for Flood Damage Work

Date:- 15-1.21.

1 Name of PIUs:- Muzattentus East-2

2 Name of Block/Road:- Country sould bipsoche Asli Penchayat from Paletainete Diala totalind

(A) For Road:

1. Damage Location/Chainage:- 15+2 2 reliones

2. Damage Length:- 1.5 12 re

- 3. Nature of Damage :- Detene & trail withy
- 4. Details of Restoration Works:
- (i) Material being used in Restoration works:
- (ii) Equipment's/Tools being used in Restoration works:
- (iii) Procedure taken up in Restoration works:
- (iv) Restored Length :- 1.1781 Kmg.

(B) For Bridge:

- 1. Damage Location/Chainage :-
- 2. Damage Length
- 3. Nature of Damage :
- 4. Details of Restoration Works :-
- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

Signature

Executive Engineer

R. W. Works Division

Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road

Construction of Road Pipraha Asli panchayat from Pakhanaha Dhala to Main Road Connectin North Side of Posan Ram, Daulat Ram, Syamnandan Ram in Bhelueepur village Mahadalit Basti

Muzaffarpur

District Block

Minapur

Division

Muzaffarpur East-2

3.600 Km

Length of Road (in Km)		AKH5)
SI. No.	DESCRIPTION	4.139
1	Jhama metal	0.000
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	4.139
,	GRAND SUB TOTAL	4.139
TOTAL C	COST OF PROJECT IN LACS =	

RWD

Techanically approved for B. 4.139 laws Chapees four Law thirteen thousand wind hundred only)