

Inspection Report for Flood Damage Work

Date:- 18.1.21

1 Name of PIUs :- Muzaffarpur East-2

2 Name of Block/Road :- Siverpatti talghosant


(A) For Road:

1. Damage Location/Chainage :- 1st & 2nd Km
2. Damage Length :- 96 m
3. Nature of Damage :- Half length road washed away & 1/2 done
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- rock bats
 - (ii) Equipment's/Tools being used in Restoration works:- Tractor
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


18.1.21
Signature
R.W.D. Works Division
(Name of Inspection)
Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Siwaipatti to Ghosaut

District Muzaffarpur

Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km) 3.010 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	7.175
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.349
	GRAND SUB TOTAL	7.524
TOTAL COST OF PROJECT IN LACS =		7.524

my
8.1.21

JE
RWD

AB
08/1/17

AE
RWD

9am
8/1/17

EE
RWD

Technically approved for Rs. 7.524 lacs
(Rupees seven lacs fifty two thousand four hundred only)

my
1.1.17

S.E.

RWD WORK circle
Muzaffarpur