

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- minapur / Alinewra PWD Road to Devi Astham Kuthwatha Bhatti  
take

### (A) For Road:

1. Damage Location/Chainage :- 0.250 km, 0.750 km, 0.990 km,
2. Damage Length :- 0.1129 km
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- Gravel
  - (ii) Equipment's/Tools being used in Restoration works:- Road roller
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :- 0.1129 km

### (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE

  
Signature

(Name of Inspection)

EG

RWD minapur Ghat - 1

### GENERAL ABSTRACT

Name of Road Alinewura PWD Road to Devi Asthan Kushwaha Basti Tak

District Muzaffarpur


Block Minapur

Division Muzaffarpur East-2


Length of Road (in Km) 2.775 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	1.486
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	1.486
TOTAL COST OF PROJECT IN LACS =		1.486


say 1.49 lac

  
9/1/21


JE  
RWD

  
11/01/21

AE  
RWD

  
EE  
11/1/21  
RWD

Technically approved for Rs 1.49 lac  
(Rupees one lac forty nine thousand only)

  
SE 13.1.21

RWD work circle  
muzaffarpur