## **Inspection Report for Flood Damage Work**

18-1-21 Date:-1 Name of PIUs: - Myzaffarful East 2 2 Name of Block/Road: - Ko Barrya Norveya Tola to chamer Tola (A) For Road: 1. Damage Location/Chainage :- 184 12109 :- 21.1 mm 2. Damage Length :- med attendue flood in mure 3. Nature of Damage 4. Details of Restoration Works :morek bets Material being used in Restoration works:-Equipment's/Tools being used in Restoration works: (i) (ii) Procedure taken up in Restoration works: (iii) :- 31.1 mts Restored Length (iv) (B) For Bridge: 1. Damage Location/Chainage 2. Damage Length 3. Nature of Damage :-4. Details of Restoration Works :-

(i) Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length

Signature of JE/AE/EE

Signature

Executive Engineer

Name of Inspection

Muzaffarpur East-1

## **GENERAL ABSTRACT**

Name of Road

Kohariya Nonoya Tola to Chamar Tola

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

1.117 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	2.677
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	2,677
TOTAL C	COST OF PROJECT IN LACS =	2.677

Bry 21

JΕ

**RWD** 

ASOSTOIM

ΑE

RWD

Clory Silly

RWD

Techanically approved for 6. 2-677 less (Pupes two lee Society Seven Thousand Seven hundred only

C.F.

RIOD WORK wiche

1943afforpur