Inspection Report for Flood Damage Work

Date:-18-1-21

2 Name of Block/Road: - VI Chayakin was chown to resolvent the of

(A) For Road:

- :- 134-22 holker 1. Damage Location/Chainage
- :- 122-2Mh 2. Damage Length
- :- cutting of 1/2 sould flower 3. Nature of Damage
- 4. Details of Restoration Works :-
- Material being used in Restoration works:- rowce beds
- Equipment's/Tools being used in Restoration works:- veetw (i) (ii)
- Procedure taken up in Restoration works: (iii)
- :- 122-2mh Restored Length (iv)

(B) For Bridge:

- 1. Damage Location/Chainage
 - 2. Damage Length
 - 3. Nature of Damage
 - 4. Details of Restoration Works :-
 - Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length

Signature of JE/AE/EE

Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road

Vidhayak Ji Near Chawk to Braham asthan Via Rajput Tola (Link No.s-158)

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

1,320 Km

Ol Na		AMOUNT (LAKHS)
SI. No.	DESCRIPTION	9.758
1	Jhama metal	0.000
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	9.758
7	GRAND SUB TOTAL	9.758
TOTAL C	OST OF PROJECT IN LACS =	9.750

RWD

RWD

RWD

Techanically approved for B. 9.758 laws

(Rupees nine law Seventy five Trousand arget thundred only)

S. E.
RNOT NOOME CINCLE
MUSAffarfur