## **Inspection Report for Flood Damage Work**

Date:-17.1.21

1 Name of PIUs: Muzafforfue & 2

2 Name of Block/Road: - Referr of road from Tengraha R-B-O rout to Marchoting

## (A) For Road:

- 1. Damage Location/Chainage
- 2. Damage Length 91.3mh
- 3. Nature of Damage Broady Approach Lutting
- 4. Details of Restoration Works :-
- Material being used in Restoration works:- Portice bats (i)
- Equipment's/Tools being used in Restoration works: (ii)
- Procedure taken up in Restoration works: (iii)
- Restored Length (iv) :- 9 1.3mm

## (B) For Bridge:

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works:
- Material being used in Restoration works:-(i)
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) Executive Engineer R.W.D. Works Division Muzaffarpur East-J

## **GENERAL ABSTRACT**

Name of Road

Repair of road from Tengraha R.E.O. road to Madhopur

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

2.200 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	8.155
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	8.155
TOTAL COST OF PROJECT IN LACS =		8.155

\$-1.57

JL

RWD

Mologoila

ΑE

**RWD** 

Jan 8/11/2

Techanically approved for & & 15 law (Rupees eight lace tipteen Thousand five hundred only)

\$.8

full took incle