

Inspection Report for Flood Damage Work

Date:- 18.1.21.

1 Name of PIUs :- Muzaffar Pur East-2

2 Name of Block/Road :- Ramehady house to Ramjan house

(A) For Road:

1. Damage Location/Chainage :- 1st km
2. Damage Length :- 40 mtr
3. Nature of Damage :- road cutting
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- brick balls
 - (ii) Equipment's/Tools being used in Restoration works:- tractor
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- 40 mtr

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)
R.W.D. Works Division
Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Ramchandrahouse to Ramjanhouse

District Muzaffarpur

Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km)

0.150 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	6.909
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	6.909
TOTAL COST OF PROJECT IN LACS =		6.909

mw
8-1-21

JE
RWD

AD
08/01/21

AE
RWD

fm
8/1/21

EE
RWD

Technically approved for Rs 6.909 lacs
(Rupees six lacs ninety thousand nine hundred only)

AD
08/01/21
S.E.

RWD work circle
Muzaffarpur