

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :-

2 Name of Block/Road :- *Haripur Bels prob damage to primary path in Pachhigai Kallah Talu*

(A) For Road:

1. Damage Location/Chainage :- *1st km*
2. Damage Length :- *98.3 mtr*
3. Nature of Damage :- *cutting of road due to flood*
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- *brick bels*
 - (ii) Equipment's/Tools being used in Restoration works:- *axe etc*
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- *98.3 mtr*

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE

[Signature]
18.1.21
Signature
Executive Engineer
(Name of Inspection)
R.W.D. Works Division
Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Harpur Baks PWD Chawk to PMGSY Path via Pachhiyari Mallah Toli

District Muzaffarpur


Block Minapur


Division Muzaffarpur East-2


Length of Road (in Km)

1.155 Km


Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	17.326
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	17.326
TOTAL COST OF PROJECT IN LACS =		17.326


JE
RWD


AE
RWD


EE
RWD

Technically approved for Rs. 17.326 Lacs
(Rupees Seventeen Lacs thirty two thousand six hundred only)


S.E.
RWD WORK CIRCLE
MUZAFFARPUR