Inspection Report for Flood Damage Work

Date:-17.1.21 1 Name of PIUs: - Muzafforfur - East 2 2 Name of Block/Road: - khantles NHz to Rountola (A) For Road: 1. Damage Location/Chainage :- 3 ad Levia, 2. Damage Length 160AV 3. Nature of Damage Cutting due to plord 4. Details of Restoration Works :-Material being used in Restoration works:- Part bats (i) Equipment's/Tools being used in Restoration works:-(ii) Procedure taken up in Restoration works: (iii) (iv) Restored Length 160mt8 (B) For Bridge: 1. Damage Location/Chainage

- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works :-
- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-

:-

- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

Signature

(Name of Inspection) R.W.D. Works Division Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road

KHORIKA NH 28 to RAMTOLA

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

3.000 Km

Length of road (in roin)		AMOUNT (LAKHS)
SI. No.	DESCRIPTION	27.542
1	Jhama metal	0.000
2	Sand Filling	0,000
3	Sand bag	0.000
4	H.P.	27.542
	GRAND SUB TOTAL	27.542
TOTAL (COST OF PROJECT IN LACS =	

1. 2. 1. 2.

RWD

Ky od oly

AE

RWD

EE PII

RWD

Techanically afformed for B. 27. 542 hees
Rupes twenty Seven lass tifty foroz Thousand two hundred only

SE

RWD Wode Circle