## **Inspection Report for Flood Damage Work**

15-1-21 Date:-

1 Name of PIUs: - Muzer Herry Bort 2

Khemkorn to Khospakn' 2 Name of Block/Road :-

## (A) For Road:

- 1. Damage Location/Chainage :- LS+ Ktor
- :- 53. om 2. Damage Length
- :- Fully seed dament 3. Nature of Damage
- 4. Details of Restoration Works :-
- Material being used in Restoration works:-(i)
- Equipment's/Tools being used in Restoration works: (ii)
- Procedure taken up in Restoration works: (iii)
- :- 53. umm Restored Length (iv)

## (B) For Bridge:

- 1. Damage Location/Chainage
- 2. Damage Length
- :-3. Nature of Damage
- 4. Details of Restoration Works :-
- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) r. Executive Engineer. R.W.D. Works Division Muzaffarpur East-1

## **GENERAL ABSTRACT**

Khemkaran chowk to khosa palcon

Name of Road

L101 - T08 Ramnagar to Paigambarpur Sonoul Tola

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

3.575 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	26,187
2	Sand Filling	0.000
3	Sand bag	0.000
4 .	H.P.	0.000
	GRAND SUB TOTAL	26.187
TOTAL C	OST OF PROJECT IN LACS =	26.187

1.27

JE

RWD

Magalal

AE

RWD

Ser Silan

**RWD** 

Technically approved for RS 26-187 lac (Rubers Twenty six lac sighteen thousand seven hundred only)

SE ....

Run word circle muserflagues