

Inspection Report for flood damage work

Date:

1. Name of PIUs-

EE RIND (w) Division, Miratpur

2. Name of Block/Road-

- Motorable of Road from Ublewa
Sara Samta to Dohai
- Panepur

A. For Road

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration -

ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works

iv Restored Length

- 62m
cut in Road, due to flood & rain

- Bricks Bats
- Tactor Roller
- Bricks Bats
- 62m

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration :

i Material being used in Restoration :


ii Equipment/Tools being used in Restoration works:

iii Procedure taken up in Restoration works :

iv Restored Length :


21.11.2020

Signature of JE/AF/EE


21/11/20


21/11/2020
Signature

(Name of Inspector)