Inspection Report for Flood Damage Work

Date:-
1 Name of PIUs: - Gyan vibraleous
1 Name of PIUs: - Gyan vibraleans 2 Name of Block/Road: - 100 to / LO42 - Barbeta Pup Red to Barbeta Remover (VR22
(A) For Road:
1. Damage Location/Chainage :- o + 470/lm
2. Damage Length :- 0.0201cm
3. Nature of Damage :-
4. Details of Restoration Works:
(i) Material being used in Restoration works:- Bottle hads
(ii) Equipment's/Tools being used in Restoration works:- Tools
(iii) Procedure taken up in Restoration works:
(iv) Restored Length :- 0.0201cm
(B) For Bridge:
1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works:
(i) Material being used in Restoration works:-
(ii) Equipment's/Tools being used in Restoration works:-
(iii) Procedure taken up in Restoration works:-
(iv) Restored Length :-

Signature of JE/AE/EE

(Name of Inspection)

Signature

BB

RWD muzaffarpur cap-1

GENERAL ABSTRACT

Name of Road

L042-Barheta PWD Rd to Barheta Ramai (VR22)

District

Muzaffarpur

Block

Katra

Division

Muzaffarpur East-2

Length of Road (in Km)

1.875 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	
	Sand Filling	0.00
4		0.00
3	Sand bag	0.00
4	H.P.	
	GRAND SUB TOTAL	4.11
y and a		4.11
OTAL CO	ST OF PROJECT IN LACS =	

84 4.118 lac

JE "ITEST

RWD

AE M. Tront

RWD

EE M

Technically approved for RS 4.118 lac.

(Rubers tour lac Eleven thousand Eight hymological enfy)

Rup work crowde muzaffers pur